

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Yolo County Planning Resources and Public Works

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Yolo County Planning Resources and Public Works

Waterway			Bank	Unit Miles
Unit No. 01 Right Bank Cache Creek			Right	0.29
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	3/30/2010 - 3/30/2010			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Planning Resources and Public Works

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Right Bank Cache Creek						Right	0.29	03/30/2010 03/30/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.01	0.29	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.722411 ° -121.807019 °	38.725792 ° -121.806507 °	16
2	0.01	0.01	Earthen Levee	Encroachments	WS	C	Prunings	38.722411 ° -121.807008 °	38.722411 ° -121.807008 °	15
3	0.01	0.13	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.722420 ° -121.806997 °	38.724034 ° -121.806655 °	17 Y
4	0.02	0.29	Earthen Levee	Vegetation	CR	M	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: no vegetation control	38.722425 ° -121.806993 °	38.725793 ° -121.806506 °	18 Y
5	0.03	0.03	Earthen Levee	Vegetation	WS	M	Elderberries are blocking visibility and flood fight capability.	38.722633 ° -121.806938 °	38.722633 ° -121.806938 °	14
6	0.03	0.06	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.722699 ° -121.806920 °	38.723001 ° -121.806864 °	19
7	0.08	0.08	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.723375 ° -121.806762 °	38.723375 ° -121.806762 °	20
8	0.13	0.13	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.723903 ° -121.806613 °	38.723903 ° -121.806613 °	6
9	0.15	0.15	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.724165 ° -121.806552 °	38.724165 ° -121.806552 °	7
10	0.17	0.17	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.724445 ° -121.806505 °	38.724445 ° -121.806505 °	8
11	0.21	0.21	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.725022 ° -121.806478 °	38.725022 ° -121.806478 °	9
12	0.24	0.24	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.725427 ° -121.806470 °	38.725427 ° -121.806470 °	10

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Planning Resources and Public Works

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank Cache Creek	Right	0.29	03/30/2010 03/30/2010	John Williamson

Levee Mile Report Line	3
Start Levee Mile	0.01
End Levee Mile	0.13
Location	Water Side
Category	Earthen Levee
Item	Vegetation
brush on water side	
johnngw_s_20100401_087.jpg	



Levee Mile Report Line	3
Start Levee Mile	0.01
End Levee Mile	0.13
Location	Water Side
Category	Earthen Levee
Item	Vegetation
brush on water side	
johnngw_s_20100401_089.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.02
End Levee Mile	0.29
Location	Crown
Category	Earthen Levee
Item	Vegetation
vegetation on crown	
johnngw_s_20100401_088.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor